




Ports of Tilbury and Tilbury2 Notice to Mariners – No. 23 of 2019

Ebb Tide Approach – Draft Restrictions

Mariners were advised that No. 3 Donut fender had been damaged and that the roller fender and pile had been temporarily removed. (Notice 21 of 2019)



No.1 and No.2 and No.4 fenders remain afloat and operational, however Mariners are advised to navigate with caution and avoid landing on the donut fenders whenever possible.

A recent survey of the remaining pile structure has shown it to be - 4.8m below CD, therefore a **draft restriction at low water of 4.5m** will be enforced on ebb tide approaches until the pile is replaced.

16/12/19

Port of Tilbury London Limited
Leslie Ford House
Essex - RM18 7EH

Capt. Geoff Holland
Chief Harbour Master



EXPIRY DATE: 01/06/20

A full list of current Notice to Mariners can be found at:-
<https://www.forthports.co.uk/marine/tilbury-port-authority/>
Telephone calls, VHF radio traffic, CCTV images may be recorded.





Ports of Tilbury and Tilbury2 Notice to Mariners – No. 23 of 2019

Ebb Tide Approach – Draft Restrictions

Please note that this is at low water only, and that the tidal rate is approx. 1m per hour with a range of 6.4m on a MHWS.

For further information please contact the Lock office on 01375 852456 or VHF ch04.

16/12/19

Port of Tilbury London Limited
Leslie Ford House
Essex - RM18 7EH

Capt. Geoff Holland
Chief Harbour Master



EXPIRY DATE: 01/06/20

A full list of current Notice to Mariners can be found at:-
<https://www.forthports.co.uk/marine/tilbury-port-authority/>
Telephone calls, VHF radio traffic, CCTV images may be recorded.

