

FORTH PORTS PLC

No 26 of 2009

24 November 2009

NOTICE TO MARINERS INNER FIRTH OF FORTH

KINCARDINE and CLACKMANNANSHIRE BRIDGES

Ref Charts: BA 741 and 737

1. A report has been received indicating that there is doubt regarding the clearances under the above referenced bridges. Pending an investigation by Transport Scotland, Upper Forth river users are advised to proceed with extreme caution when transiting these bridges and to allow a clearance under them of 13.0m above chart datum (7.2m above HWS) until further notice.
2. In addition please be advised that the navigation span of the Clackmannanshire Bridge is not marked with navigation lights.

Status of previously published notices:

No 1 of 2000 remains in force

No 14 of 2006 remains in force

No 20 of 2007 remain in force

Nos 8, 10, 13, 20, 21 and 22 of 2008 remain in force

Nos 1, 3, 7, 9, 13, 15, 16, 17, 23 and 24 of 2009 remains in force

R BAKER
Chief Harbour Master