

Marine Safety Alert



Alert No: 011

Date: 08/09/2015

Working Outside Railings



During a recent Port Marine Safety Code liaison meeting with one of our major terminal operators on the river, it has been brought to our attention that there has been a marked increase of personnel not following the correct procedures for working outside railings.

This kind of work should only be undertaken if there is no reasonably practicable alternative to doing so.

We cannot stress enough the importance of working **safely** aloft or overboard.

It is a must that all risk assessments & safety precautions are in place **before any** work is commenced.

FORTH PORTS LIMITED	Document ID FP PMSC F21_01	Authorised By MM	Original Date June 2013
MARINE SAFETY ALERT	Date Revised	Revised By	Review Due June 2016