



Ports of Tilbury and Tilbury2 Notice to Mariners – No.12 of 2021

TILBURY LOCK - EBB TIDE DOCKING RESTRICTION THIS NOTICE SUPERCEDES NO.10 OF 2021

Mariners are advised the No.1 and No.3 roller fender are inoperable. The Roller fenders are numbered 1 to 4, No.1 being closest to the outer lock gates.

Due to the inoperable roller fenders, it is necessary to place restrictions on Tilbury Lock arrivals, as detailed below:

- Tilbury Lock bow first ebb tide arrivals are not permitted
- Tilbury Lock stern first ebb tide arrivals are not permitted for vessels of 200m LOA and above
- Tilbury Lock stern first ebb tide arrivals are permitted for vessels less than 200m LOA
- Tilbury Lock flood tide arrivals are unaffected
- Tilbury Lock departures on the flood and ebb tide are unaffected

Light tugs and inland waterways vessels are considered on a case by case basis.

For further information please contact the Lock office on +44 (0) 1375 852456 or VHF 04.

18/11/21

Port of Tilbury London Limited
Leslie Ford House
Essex - RM18 7EH

Asset Manager Marine



EXPIRY DATE: N/A

A full list of current Notice to Mariners can be found at:-
<https://www.forthports.co.uk/marine/tilbury-port-authority/>
Telephone calls, VHF radio traffic, CCTV images may be recorded.

