

FORTH PORTS LIMITED

No. 23 of 2022

4th August 2022

NOTICE TO MARINERS

FIRTH OF TAY

Middle Bank Buoy repositioned

Mariners are advised that the Middle Bank east cardinal buoy has been repositioned to position 56° 27.453'N 002° 56.294'W.

The light characteristic of this buoy is Q (3) 10s, visibility 3,5NM.

Vessels are to navigate with caution in the vicinity of the buoy.

Port of Dundee Notices in force:

02/2021; 05/2021; 31/2021; 01/2022; 04/2022; 13/2022; 20/2022; 21/2022 and 22/2022 remain in force.

Andrew Blake
Marine Manager Dundee