

FORTH PORTS LIMITED

NTM No 26 of 2024

19th Oct 2024

NOTICE TO MARINERS FIRTH OF TAY

Fairway Buoy Unlit and Top Structure Missing

Mariners are advised that the Fairway Buoy in position 56° 28.4'N 002° 36.6'W has suffered damage resulting in the loss of its top structure, topmarks and light. Mariners are advised to navigate with caution in the area.

This notice will be cancelled once repairs are effected.

Status of previously published notices:

15/2024, 18/2024, 24/2024 and 25/2024 remain in force

Issued by:

Andrew Blake
Marine Manager Dundee