NTM No 31 of 2024 11th Nov 2024

NOTICE TO MARINERS FIRTH OF TAY

River Tay Buoyage Re-instated

Mariners are advised that following a review of Aids to Navigation, the following amended buoyage is now in place on the River Tay. Except where specifically mentioned below all of the remainder of the buoyage is as charted:

Name	Action	Position		Light
Tay Fairway	New position	56°28.909'N	2°37.343'W	LFI 10s
Outer Green	New position and new name	56°28.268'N	2°38.547'W	Fl.G 3s
Outer Red	New position and new name	56°28.093'N	2°38.098'W	Fl.R 3s
Abertay Buoy (HFP)	New position	56°27.613'N	2°39.409'W	FIQ(3)10s
Middle Red	New position and new name	56°27.329'N	2°38.958'W	Fl.R 6s
Inner Green	New position	56°27.400'N	2°41.080'W	Fl.G 12s
Inner Red	New position	56°27.073'N	2°41.007'W	Fl.R 12s
Lady Green	New name (formerly North Lady)	56°27.390'N	2°46.850'W	Q.G
Lady Red	New name (formerly South Lady)	56°27.200'N	2°46.840'W	Q.R
Pool Red	New name (formerly Pool South)	56°27.135'N	2°48.520'W	FL.R 6s
Outer Radio Reporting Point	New position	56°28.591'N	2°37.861'W	
Outer Pilot Boarding Point	New position	56°28.741'N	2°37.677'W	



Status of previously published notices:

15/2024 and 18/2024 remain in force

Issued by: Andrew Blake

Marine Manager Dundee