

PORT OF DUNDEE LIMITED
Via e-mail

No. 03 of 2021

9th February 2021

NOTICE TO MARINERS

FIRTH OF TAY

Middle Buoys Position Unreliable

Mariners are advised that the Middle Green Buoy, charted position - 56° 28.169'N 002° 38.251'W and the Middle Red Buoy, position - 56° 27.524'N 002° 37.570'W. Have been reported as being out of position.

All vessels transiting the area should navigate with caution and consider both of the Middle Buoys observed positions as unreliable. The Buoys will be returned to their charted positions as soon as is reasonable practicable.

Further information can be obtained by contacting the port office or Dundee Harbour Radio of VHF Ch12

Ryan Porteous
Harbour Master
Port of Dundee

Port of Dundee

Notices in force:

**09/2020; 11/2020; 16/2020; 20/2020; 21/2020; 29/2020; 31/2020; 33/2020; 35/2020;
37/2020
02/2021**