

FORTH PORTS LIMITED

NTM No 52 of 2021

23rd September 2021

NOTICE TO MARINERS FIRTH OF FORTH

Buoy off Location – Firth of Forth

Mariners are advised that the Grangemouth No.2 Buoy (Fl.G.4s) is currently off position.

Attempts will be made to locate and recover the buoy at the earliest opportunity.

Mariners are advised to navigate with extra caution in this area and to report any uncharted buoys to FTNS on 01324 498586.

A temporary replacement buoy will be positioned on station as soon as possible.

Status of previously published notices:

No 10 and 45 of 2019 remain in force

No 04, 07, 23 and 64 of 2020 remain in force

No 06, 07, 14, 26, 32, 46 and 51 of 2021 remain in force

Issued by

Greg Macintyre

Marine Manager

